

## CURRENT TO PRESSURE MEASUREMENT TRAINER MAKE – LABTEK, ORIGIN – INDIA



Current to Pressure Trainer. This setup comprises of a I to P converter fitted on a base. Two pressure gauges are fitted one at the input side and the other at the output of the I to P converter. A current source with digital display is provided to excite the I to P converter. A constant air supply should be provided to the system at 20 Psi Pressure from a standard compressor