

PRESSURE TO CURRENT MEASUREMENT TRAINER MAKE – LABTEK, ORIGIN – INDIA



Pressure to Current (P to I) Trainer: This setup comprises of pressure chamber fitted on a base board. A pressure transducer and bourdon pressure gauge are fitted to the chamber. Digital pressure indicator with transmitter output is provided to display the pressure sensor by the pressure transducer. Transmitter output 4 to 20mA can be measured by a current meter. Foot air pump is provided to build the pressure.