

LOAD FRAME, HAND OPERATED, 50 KN
MODEL NO SL -GT - 065, MAKE - LABTEK, ORIGIN - INDIA



Triaxial Setup

Triaxial setup has different main components. These components are selected to complete the setup. In the following pages specifications are given of each components. Main component requirement for this test are:

- i) Load Frame**
- ii) Triaxial Cell**
- iii) Lateral Pressure Assembly**
- iv) Measuring Unit**